Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 10/2/2013, 10/3/2013	Man Days: 2
Inspection Unit: Macomb	•
Location of Audit: Macomb	
Exit Meeting Contact:	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Donald Hankins,	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	
·	

CONSTRUCTION INFORMATION			
Location of Construction:		Construction Pe	rformed By:
514 West Washington Street, Macomb, Illir	nois	Ameren Illinois C	rew
Contractor Foreman:	No contractor on the job site.		
Operator Inspector:	Chris Juliusson		
	Person(s) On J	ob Site	
Mike Pershing	Rick Brumb	ру	

Description of Construction:

The Ameren crew was replacing isolated service risers at the meter set. The old steel risers were replaced by installing new plastic risers and electro fused on to the plastic service line. The new risers were air tested at 100 psig for 10 minutes with no leaks being found.

SERVICE INSTALLATION		Status
[192.55]	Steel	No
General Comment:	•	·
No steel was installed during this audit		
[192.59]	PE	Yes
[192.59]	Other	No
General Comment:	<u> </u>	<u> </u>

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

No other pipe was installed at this job site.		
[192.619,192.621,192.623]	MAOP	60 psig
[192.5]	Class location :	Class 2
[192.53]	Are components qualified for use?	Satisfactory
[192.63(a)(2)]	Pipe Size :	1/2" Plastic
[192.55,192.59]	Specification:	ASTM D- 2513
[192.55,192.59]	Manufacturer :	Driscoplex
[192.55,192.59]	Pipe Grade :	PE 2404/2708
[192.55,192.59]	Wall Thickness :	.090
[192.63]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
[192.227]	Welder qualification date:	Not Applicable
General Comment:		
No welding on this job site.		
[192.227]	Welder's Name:	Not Applicable
General Comment:		
No welding on this job site.		
[192.225,192.275,192.277,192.279,192.283	Is pipe joined in accordance with approved written procedures?	Satisfactory
[192.285]	Date of Qualification :	1-23-13
[192.285]	Joiner's name:	Mike Pershing
[192.455]	Is buried metallic pipe coated?	Not Applicable
General Comment:		
No metallic pipe used during this audit		
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
General Comment:		
No cathodic protection on this line, it is plastic		
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
General Comment:		
This is a plastic system no cathodic protection on this li	ne.	
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	No
General Comment:		
This is a plastic system no cathodic protection on this line.		

AMEREN ILLINOIS COMPANY/10-3-2013

Page 2 of 5

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.461]	Does coating meet 192.461?	Not Applicable
General Comment:		
This is a plastic system.		
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:	•	
This is a plastic system.		
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Satisfactory
General Comment:		
Above ground piping is clean and painted	1.	
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
No underground metallic structures in the	e area of this job.	
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
[192.321]	Does plastic pipe have means of locating while underground?	Satisfactory
[192.325]	Are required clearances from underground structures being maintained?	Not Applicable
General Comment:		
No other underground structures in the a	rea.	
Is required cover being obtained	for the service line?	Satisfactory
[192.503]	Are general testing requirements being met?	Satisfactory
[192.517]	Are records being made of strength and leak tests?	Satisfactory
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
[192.805(c)]	Were non-qualified personnel being "directed and observed" by a qualified individual?	Not Applicable
General Comment:		
All employees were qualified for this job.		
[192.805(c)]	Were span of control limitations being followed?	Not Applicable
General Comment:	·	
All employees' were qualified.		

AMEREN ILLINOIS COMPANY/10-3-2013

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Was a Protocol 9 (Form 15) Completed?		No
General Comment:		
A protocol 9 was not completed during this audit.		
[192.614]	Were One Call Notifications performed as required?	Satisfactory
[192.614]	Dig Ticket #	X2691480
[192.383(b)]	Is an EFV installed on any new or replaced service line serving a single-family residence?	Not Applicable
General Comment:		
No EFV valve was installed the line was dug up at the house only.		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.